

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L5	1051	((strobe\$1 near3 edge\$1) and (decrement\$4 or increment\$4 or invert\$\$ or pull \$4) and (clock near3 signal) and phase\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/10/08 11:01
L6	115	((strobe\$1 near3 edge\$1) and (decrement\$4 or increment\$4 or invert\$\$ or pull \$4) and (clock near3 signal) and phase\$1) and ((measur\$4 or test\$4 or comput \$4) near3 parameter\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/10/08 11:02
L7	119	((strobe\$1 near3 edge\$1) and (decrement\$4 or increment\$4 or invert\$\$ or pull \$4) and (clock near3 signal) and phase\$1) and ((measur\$4 or test\$4 or comput \$4 or compar\$4) near3 parameter \$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/10/08 11:02

L8	92	((strobe\$1 near3 edge\$1) and (decrement\$4 or increment\$4 or invert\$\$ or pull \$4) and (clock near3 signal) and phase\$1) and ((measur\$4 or test\$4 or comput \$4 or compar\$4) near3 parameter \$1) and ((determin\$4 or indicat\$4) near3 (error\$1 or failure \$1))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/10/08 11:04
L9	200	((strobe\$3 near2 (data or edge \$1)) and (decrement\$4 or increment\$4 or invert\$\$ or pull \$4) and (clock near3 signal) and phase\$1) and ((measur\$4 or test\$4 or comput \$4 or compar\$4) near3 parameter \$1) and ((determin\$4 or indicat\$4) near3 (error\$1 or failure \$1))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/10/08 11:05
L13	59	((strobe\$3 near2 (data or edge \$1)) and ((decrement\$4 or increment\$4 or invert\$3 or pull \$4) same (clock near3 signal))) and ((measur\$4 or test\$4 or comput\$4 or compar\$4) near3 parameter\$1) and ((determin\$4 or indicat\$4) near3 (error\$1 or	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/10/08 11:08

		failure\$1))				
L14	3	(((strobe\$3 near2 (data or edge\$1)) same ((decrement\$4 or increment\$4 or invert\$3 or pull \$4) same (clock near3 signal)))) and ((measur\$4 or test\$4 or comput\$4 or compar\$4) near3 parameter\$1) and ((determin\$4 or indicat\$4) near3 (error\$1 or failure\$1))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/10/08 11:24
L15	0	(((strobe\$1 near3 edge\$1) and (decrement \$4 or increment \$4 or invert\$\$ or pull\$4) and (clock near3 signal) and phase \$1) and ((measur \$4 or test\$4 or comput\$4 or compar\$4) near3 parameter\$1)). clm.	US-PGPUB	OR	OFF	2008/10/08 11:25

10/ 8/ 08 11:26:00 AM

C:\ Documents and Settings\ EAbraham\ My Documents\ EAST\ Workspaces  
\ newformat.w sp